

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Thahar to Lorempur</u>		
Hazards: <u>Flood/Rain</u>		
Division: <u>Madhubani</u>	District: <u>Madhubani</u>	Actual Length (in km): <u>2.630</u>
Damage Length (in km): <u>0.788</u>	Damages Location/Chainage: <u>photo attached</u>	
Name of Scheme/Programme: <u>old MIA</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameter's to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	<u>U</u>
a)	Condition of Surfacing	<u>U</u>
Description of observation : <u>Laying and rolling temp. of MSS not maintained. Compaction of MSS poor</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation :		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>N/S</u>
Description of observation :		
e)	Compaction of flanks/ slope & rain.	
Description of observation: <u>E/W in flanks not done.</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	<u>NIA</u>
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: <u>Laying and rolling temp. of MSS not maintained. Compaction of MSS poor.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Name of Officer: KUMAR RAKESH

Designation: सकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

Recd
31/7/21
AE

(Signature)

03.07.21