

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Dighwa Geth to Ekderawan hote me Sonaulia Dhala Tak</u>		
Hazards	Flood/Rain Flood	
Division: <u>Gopalganj - 2</u>	District: <u>Gopalganj</u>	Actual Length (in km): <u>3.00</u>
Damage Length (in km): <u>approx. 0.500</u>	Damages Location/Chainage: <u>Approx 2nd Km, 1.1 to 1.60</u>	
Name of Scheme/Programme:	<u>Old scheme</u>	
Status of Project:	<u>Under Agreement/Out of Agreement</u> <u>out of Agreement.</u>	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<u>S</u>
Description of observation : <u>Approx 2nd 500 m length of the road 20mm MSS done.</u>		
b)	Adequate Thickness of pavement layers constructed	
Description of observation : <u>Below MSS work, pot patch with GSB & II LWB & III material work done.</u>		
c)	Quality of Construction Material Used	
Description of observation : <u>MSS material quality is satisfactory.</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation : <u>No undulation in surface.</u>		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : <u>No rain cuts in flanks.</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>O.K.</u>
b)	Condition of Vent Clearance	<u>clear.</u>
c)	Condition of railings/Slab/approach for Bridges	<u>—</u>
Description of observation of CD works : <u>In Hume pipe Culvert, Vent is clear.</u>		
Remark if any: <u>Due to rain water logged occur in some parts in both sides of the road.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory (S)

Name of Officer: Rana Barun Kumar Singh.

Designation: Executive Engineer.

[Signature] 02.03.2024
(Signature)