INSPECTION	REPORT FOR FLOOD /RAIN DAMAGE	ROAD
Name of Scheme: Possasa	F V . I/ DUYA	
Hazards	Flood/Ports Floor	
Division: Gopalgary - 2	Chainage: HDP	10 3 30
Damage Length (in km): Appar	I am try	
Name of Scheme/Programme:	Linday Agreement/Out of Agreement	India.
Status of Project:	Parameters to be Checked in Restoration work	Remarks : (S/U)
Sr. No.	Pavement (BT/CC)	
1.	Condition of Surfacing	
a)  Description of observation:	No Swift work done till the t	ime of Inspection
	Adequate Thickness of pavement layers constructed	
b)	1 L L CO OLT	I WBM26II
Description of observation:	patch work olone in the onso fre	W mond.
Markey	patch work done in the dampe langer of	THE OUT
	Quality of Construction Material Used	
c)  Description of observation:	ality of WBM & III & GSB 36 II material Used	with is Safe from
d) :	L W. stor from any defects and Irregularity example-	T
<b>u</b> ) :	Surface Cracks, Undulation, exposed aggregates in case o CC Pavement, Poor workmanship, etc.	<u>'</u>
Description of observation:		•
	Compaction of flanks/ slope & raincuts	<u> </u>
e)  Description of observation:	No vain cuts in flant.	
	Cross Drainage Structure	
2	Condition of head walls in Hume pipe culverts	-
a)	Condition of Vent Clearance	44
b)	Condition of railings/Slab/approach for Bridges	
C)		
Description of observation of CD  Remark if any: Swfall		•
Overall Rating	Satisfactory (S) / Unsatisfactory (U)	ushilados (U

Name of Officer: Rana Bayun. Kunner Singh.
Designation: Emelotive Enfiners.

(Signature) 103.202