

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: *L029-Tab Mathiya to Dighura Dubauli*

Hazards: *Flood*

Division: *Gopalganj-2*

District: *Gopalganj*

Actual Length (in km): *3.0*

Damage Length (in km): *approx. 0.350*

Damages Location/Chainage: *In 2nd km approx 1.305-650*

Name of Scheme/Programme: *PMGSY*

Status of Project:

Under Agreement/Out of Agreement *Out of Agreement*

Sr. No.

Parameters to be Checked in Restoration work

Remarks : (SU)

I.

Pavement (BT/CC)

a)

Condition of Surfacing

S

Description of observation :

In Approx 350m length of the road, 20mm MSS work done on surface.

b)

Adequate Thickness of pavement layers constructed

Description of observation :

Below MSS work pot patch work in the L&B go II and WBM go III material done.

c)

Quality of Construction Material Used

Description of observation :

Quality of MSS material is Satisfactory

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation :

No undulation in surface

e)

Compaction of flanks/ slope & raincuts

Description of observation :

No rain cuts in flank.

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

c)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory (S)

Name of Officer: *Rana Baam Kumar Singh*

Designation: *Executive Engineer.*

[Signature]
(Signature)