

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Devkuli NH 101 to Hakam Bazar		
Hazard's: Flood/Rain Flood		
Division: Gopalganj - 2	District: Gopalganj	Actual Length (in km): 2.24
Damage Length (in km): Approx 0.150	Damages Location/Chainage: 2nd Km approx 0.005 to 0.105 2.2nd Km approx 1.4 to 1.45	
Name of Scheme/Programme: MMBSR		
Status of Project: Under Agreement/Out of Agreement Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S
Description of observation : In Approx 150m length of the road, 20mm MSS work done on surface.		
b)	Adequate Thickness of pavement layers constructed	
Description of observation : Below MSS work, pot patch work with GSB 90II and WBM 90III material done.		
c)	Quality of Construction Material Used	
Description of observation : Quality of MSS material is Satisfactory.		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation : No undulation in surface.		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : No raincuts in flanks.		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	-
b)	Condition of Vent Clearance	Clear
c)	Condition of railings/Slab/approach for Bridges	-
Description of observation of CD works : -		
Remark if any: -		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory (S)

Name of Officer: **Rana Rakesh Kumar Singh.**

Designation: **Executive Engineer.**

03.03.2021
(Signature)