

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Alalpatte Rly Gunti to Rajepura Indira Colony</u>		
Hazards	Flood/Rain	
Division: <u>Darbhanga-1</u>	District: <u>Darbhanga</u>	Actual Length (in km): <u>1.900 km</u>
Damage Length (in km): <u>1.80 km</u>	Damages Location/Chainage: <u>-</u>	
Name of Scheme/Programme: <u>FDR</u>		
Status of Project:	Under Agreement/Out of Agreement <u>Out of Agreement</u>	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<u>U</u>
Description of observation : <u>In the DPR, there is provision for 20mm MSS in 900m Length & 160mm CC work in 900m Length. But No BT and CC work done.</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation : <u>Patch work is done with Adequate thickness in BT portion only.</u>		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation : <u>Good.</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>U</u>
Description of observation : <u>In 0 to 600 metre length restoration work is not done due to water logging and traffic congestion.</u>		
e)	Compaction of flanks/ slope & raincuts	<u>-</u>
Description of observation : <u>No provision in the scheme</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>-</u>
b)	Condition of Vent Clearance	<u>-</u>
c)	Condition of railings/Slab/approach for Bridges	<u>-</u>
Description of observation of CD works : <u>No provision in the scheme.</u>		
Remark if any: <u>In about 600 m from start (ie from Alalpatte Rly Gunti) Restoration work is not done due to water logging and due to traffic congestion. Rest portion of the road is restored with WBM-63.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Name of Officer:

Ram Prabesh Saw

Designation:

T.A, RWD
Work Circle Siwan

(Signature)

11/5.7.21

and
5/2/21
AC