

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Jagdishpur to Machhargawan

Hazards: Flood/Rain

Division: Betna

District: West Champaran

Actual Length (in km): 7.350 km

Damage Length (in km): 0.816 km

Damages Location/Chainage: 0.050 km, 0.500 km

Name of Scheme/Programme:

FDR (3054)

Status of Project:

Under Agreement/Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks : (S/U)

1.

Pavement (BT/CC) BT

a)

Condition of Surfacing

S

Description of observation :

MSS surfacing work is in good condition

b)

Adequate Thickness of pavement layers constructed

S

Description of observation :

GSB - 100 mm

WBM GSB - 75 mm

MSS - 20 mm

c)

Quality of Construction Material Used

S

Description of observation :

Good quality material used

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

N.A.

Description of observation :

N.A.

e)

Compaction of flanks/ slope & raincuts

S

Description of observation :

Flank is in good condition

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

S

b)

Condition of Vent Clearance

S

c)

Condition of railings/Slab/approach for Bridges

N.A.

Description of observation of CD works :

CD work found in good condition.

Remark if any:

Work is in good condition

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: Ratnesh Paswan

Designation: E.E.

Signature
10/7/21
A.E.

(Signature)

E.E.