

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>Bethlah Nawalpur - Kharatia Nawalpur</u>		
Hazards: <u>Flood/Rain</u>		
Division: <u>Betra</u>	District: <u>West Champaran</u>	Actual Length (in km): <u>12.560 km</u>
Damage Length (in km): <u>0.353 km</u>	Damages Location/Chainage: <u>1.50 km, 7.500 km, 8.400 km</u>	
Name of Scheme/Programme: <u>FDR (3054)</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) <u>BT</u>	
a)	Condition of Surfacing	<u>S</u>
Description of observation : <u>MSS surfacing work is in good condition</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation : <u>CSB - 100mm</u> <u>WBM Gb III - 75mm</u> <u>MSS - 20mm</u>		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation : <u>Good quality material used</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>N.A.</u>
Description of observation : <u>N.A.</u>		
e)	Compaction of flanks/ slope & raincuts	<u>S</u>
Description of observation : <u>Flank is in good condition</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>S</u>
b)	Condition of Vent Clearance	<u>S</u>
c)	Condition of railings/Slab/approach for Bridges	<u>N.A.</u>
Description of observation of CD works : <u>CD work found in good condition</u>		
Remark if any: <u>work is in good condition</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>S</u>
---------------------------------------	----------

Name of Officer: Ratnesh Paswan

Designation: E.E.

10.7.21
(Signature)

E.E.

10/7/21
A.E.