

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Dairy Farm to Kura Belderi

Hazards Flood/Rain

Division: Belra

District: West Champaran

Actual Length (in km): 1.00 km

Damage Length (in km): 0.200 km

Damages Location/Chainage: 0.400 km

Name of Scheme/Programme:

FDR (3054)

Status of Project:

Under Agreement/Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks: (S/U)

1.

Pavement (BT/CC) CC

a)

Condition of Surfacing

S

Description of observation:

PCC work is in good condition

b)

Adequate Thickness of pavement layers constructed

S

Description of observation:

PCC - 160 mm

c)

Quality of Construction Material Used

S

Description of observation:

Good quality material used.

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

N.A.

Description of observation:

N.A.

e)

Compaction of flanks/ slope & raincuts

Description of observation:

Flank work is in progress

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

N.A.

b)

Condition of Vent Clearance

N.A.

c)

Condition of railings/Slab/approach for Bridges

N.A.

Description of observation of CD works:

N.A.

Remark if any:

work is in good condition

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: Ratmesh Paswan

Designation: E.E.

Signature
E.E.
11.7.21

Signature
11/7/21
AE