

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Bhelali - Nonia to Budhi Mai</u>		
Hazards	Flood/Rain	
Division: <u>Raxaul</u>	District: <u>Motihari</u>	Actual Length (in km): <u>0.8</u>
Damage Length (in km): <u>0.870</u>	Damages Location/Chainage: <u>0, 0.800</u>	
Name of Scheme/Programme: <u>EDR</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	
Description of observation : <u>Good</u>		
b)	Adequate Thickness of pavement layers constructed	
Description of observation : <u>M.S.S. 20mm thickness</u>		
c)	Quality of Construction Material Used	
Description of observation : <u>Good</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : <u>Flank work is damaged due to flood water. Needs to be repaired.</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: <u>Flank work to be repaired.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Manish Pd Gupta

Designation:

EE, Regional Lab, RWD
Purnea

CHB
(Signature)