

# INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Ghazipur more (Joka) to Magurahan Pakk via Vetampur.

Hazards: Flood/Rain

Division: Muz-East-2

District: Medak

Actual Length (in km): 5.700

Damage Length (in km): 0.102

Damages Location/Chainage: 0 to 5.700 K.M.

Name of Scheme/Programme:

F.D.R.-305A

Status of Project:

Under Agreement/Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks: (S/U)

1.

Pavement (BT/CC)

a)

Condition of Surfacing

Description of observation: 0 to 3.50 K.M. Road submerged in flood.  
3.70 K.M to 5.700 K.M patch work done in difference place.

b)

Adequate Thickness of pavement layers, constructed

Description of observation:

At chainage 3.70 K.M. → W.B. Wearing - I - 100 mm.  
W.B. Wearing - II - 75 mm.  
M.S.S. - 20 mm.

c)

Quality of Construction Material Used

Description of observation:

S

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation:

N.A.

e)

Compaction of flanks/ slope & raincuts,

Description of observation:

S

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

c)

Condition of railing/Slab/approach for Bridges

Description of observation of CD works:

N.A.

Remark if any

Overall Rating:

Satisfactory (S) / Unsatisfactory (U)

U

Name of Officer

Bindu Rajak

Designation

Executive Engineer

R.W.D. Regional Laboratory Dharbhanga

10/07/21  
A.E.

(S)

10/07/21