INSPECTI		ROAD ROKHTULE
Name of Scheme: Mainat	and Read via Bhangaha Graun Poth and fu	il maramata wor
Hazards	District: Work Chambaran Actual Length (in km): 2.145	
Division: Narkatiya gang	District: West Chambaran Actual Length (in kn 0.034 Damages Location/Chainage: C4 - 0.	
	Damingeo	
Name of Scheme/Programme Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	The state of the s
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	
Description of observation :		
c)  Description of observation :	Quality of Construction Material Used	-
d)	Whether free from any defects and Irregularity example-	
a)	Surface Cracks, Undulation, exposed aggregates in case of	ē —
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	_
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	S
C)	Condition of railings/Slab/approach for Bridges	
Description of observation of Remark if any:		•
soti	c. slab culvent abutment work placery. Due to flood deck slab	has been not co
Overall Rating		
		(0)
Sin Kant pra	Satisfactory (S) / Unsatisfactory (U)	2
Name of Officer:	CIA	393
2	11/07/21 A.G.	E.E.