

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: L064 Telta Hat V2a Ghasipara to Bohar to Fatehpur		
Harards	Flood/Rain Flood	
Division: Barsal	District: Katihar	
Damage Length (In km): 0.065	Damages Location/Chainage:	Actual Length (In km): 2.826
Name of Scheme/Programme:		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	
1.	Pavement (BIT/CC)	Remarks : (S/U)
a)	Condition of Surfacing	BT
Description of observation :		S
Surface found in good Cond'tion.		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
Adequate thickness found		
c)	Quality of Construction Material Used	S
Description of observation :		
Good quality of Material used.		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation :		
NA		
e)	Compaction of flanks/ slope & raincuts	S
Description of observation :		
Found in good Cond'tion.		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
NA		
Remark if any:		
Overall Rating		
Satisfactory (S) / Unsatisfactory (U)		S

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

11/7/21  
AE

11/7/21  
(Signature)