INSPECTION	REPORT FOR FLOOD RAIN DAMAGE RE	OAD
	iga to Trilokwa rath and full Ma	ra male work
Hazards	Flood/Rain	
Division: Narkatiyagang	District: West Champaran Actual Length (in km): 11.00	
Damage Length (in km): 0.	315 Damages Location/Chainage:	
Name of Scheme/Programme:	FDR	
Status of Project:	Under Agreement/Out of Agreement	1 10/10
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	The second section is
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	
Description of observation :		
c) Description of observation :	Quality of Construction Material Used	
d)	Whether free from any defects and irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	_
Description of observation:		
	Compaction of flanks/ slope & raincuts	1 —
e)	Compaction of matics stope to tantent	
Description of observation:		
2	Cross Drainage Structure	5
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	S
C)	Condition of railings/Slab/approach for Bridges	
Approck were	ongoing.	
	hab culvert complete work on going.	
Overall Rating		
	Satisfactory (S) / Unsatisfactory (U)	5
Name of Office:	CAP .	33

11/4/2021