

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: REO Road to Panchamwa Path and Pull Maramali Work

Hazards: Flood/Rain

Division: Naxkatiyaganj District: West Champaran Actual Length (in km): 13.07 km.

Damage Length (in km): 0.475 Damages Location/Chainage:

Name of Scheme/Programme: FDR

Status of Project: Under Agreement/Out of Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks : (S/U)

1. Pavement (BT/CC)

a) Condition of Surfacing

Description of observation :

b) Adequate Thickness of pavement layers constructed

Description of observation :

c) Quality of Construction Material Used

Description of observation :

d) Whether free from any defects and irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation :

e) Compaction of flanks/ slope & raincuts

Description of observation :

2 Cross Drainage Structure S

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance S

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works : 2 Nos R.C.C slab at culvert complete

Approach work on going.

Remark if any: 2 Nos R.C.C slab culvert complete

Approach work on going.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Sri Kant Prasad

Name of Office:

E.E

11/7/21
A.E

11/7/21