

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Dumra Via Amwa karariya Jagis Adiya Pul Road

Hazards

Flood/Rain

Division : Motihasi

District: Purvi Champaran

Actual Length (in km): 10.490 km

Damage Length (in km): 0.300 km

Damages Location/Chainage:

Name of Scheme/Programme:

FDR

Status of Project:

Under Agreement/Out of Agreement

Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks : (S/U)

1.

Pavement (BT/CC)

a)

Condition of Surfacing

S

Description of observation :

20 MM Mix seal surface in length 300 metre done.

b)

Adequate Thickness of pavement layers constructed

S

Description of observation :

75MM WBM Gr-II in patch done.
20 MM Mix seal surface in length 300 metre done.

c)

Quality of Construction Material Used

Description of observation :

Good quality.

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

S

Description of observation :

e)

Compaction of flanks/ slope & raincuts

Description of observation :

No provision in the scheme.

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

S

b)

Condition of Vent Clearance

S

C)

Condition of railings/Slab/approach for Bridges

S

Description of observation of CD works :

R.C.C Box culvert constructed.

Remark if any:

Restoration work completed.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer:

Ram Prabesh Saw

Designation:

TA, RWD
Work Circle Siwan

(Signature)

12.7.21

12/7/21
AC