

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Molamabue Khuradhar to Mansi Tola
 Hazards: Flood/Rain Flood
 Division: Borsol District: Katihar Actual Length (in km): 4.218
 Damage Length (in km): 0.069 Damages Location/Chainage:

Name of Scheme/Programme:
 Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) <u>BT</u>	
a)	Condition of Surfacing	<u>S</u>

Description of observation : BT Surface found in good condition.

b)	Adequate Thickness of pavement layers constructed	<u>S</u>
----	---	----------

Description of observation : Adequate Thickness found

c)	Quality of Construction Material Used	<u>S</u>
----	---------------------------------------	----------

Description of observation : Good quality of Material used

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
----	---	--

Description of observation : NA

e)	Compaction of flanks/ slope & raincuts	
----	--	--

Description of observation : Work in Progress.

2	Cross Drainage Structure	
---	--------------------------	--

a)	Condition of head walls in Hume pipe culverts	<u>NA</u>
----	---	-----------

b)	Condition of Vent Clearance	<u>S</u>
----	-----------------------------	----------

c)	Condition of railings/Slab/approach for Bridges	<u>NA</u>
----	---	-----------

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>S</u>
---------------------------------------	----------

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

(Signature)
11/07/24
 (Signature)

(Signature)
11/07/24
 A.E.