

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: <u>Prayagwari to Benu</u>			
Hazards	Flood/Rain		Actual Length (in km): <u>4.00</u>
Division: <u>MZP east-2</u>	District: <u>Muzaffarpur</u>		Damages Location/Chainage: <u>0 to 4.00</u>
Damage Length (in km): <u>3.250</u>		Name of Scheme/Programme: <u>FDR-305A</u>	
Status of Project:		Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		S
a)	Condition of Surfacing		
Description of observation : <u>0 to 3.0 km - B.T</u> <u>3.00 to 3.250 P.C.C</u> <u>3.25 to 4.00 km - B.T</u>			
b)	Adequate Thickness of pavement layers constructed		
Description of observation :	<u>MSBWR-I - 100 mm</u> <u>WR-III - 75 mm</u> <u>MSS - 20 mm</u>		<u>P.C.C. Thickness - 160 mm</u>
c)	Quality of Construction Material Used		
Description of observation :			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.		
Description of observation :			
e)	Compaction of flanks/ slope & raincuts		
Description of observation :			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		
b)	Condition of Vent Clearance		
c)	Condition of railings/Slab approach for Bridges		
Description of observation of CD works :			
Remark if any:			
Overall Rating			
Satisfactory (S) / Unsatisfactory (U) <u>S</u>			

Name of Officer

Designation

Bimal Rajak
Executive Engineer
R.W.D.
Regional Lab. Darbhanga

13/07/21
A.E.

13/07/21
(S)