

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: <u>L633 to 2 Deggun Lalnua to Paradi</u>			
Hazards		Flood/Rain <u>Flood</u>	
Division: <u>MVZ-East-2</u>		District: <u>Muzaffarpur</u>	Actual Length (in km): <u>2.40</u>
Damage Length (in km): <u>1.00</u>		Damages Location/Chainage:	
Name of Scheme/Programme:		<u>FDR 3054</u>	
Status of Project:		Under Agreement/Out of Agreement <u>0 to 2.40K</u>	
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC) <u>BT</u>		
a)	Condition of Surfacing		<u>S</u>

Description of observation :

b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation : <u>Thickness taken at 65m</u> <u>GSB Gr-I → 100mm</u> <u>WBM Gr-III → 75mm</u> <u>MSS → 20mm</u> <u>total - 195mm</u>		
c)	Quality of Construction Material Used	<u>S</u>

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>NA</u>
----	---	-----------

Description of observation :

e)	Compaction of flanks/ slope & raincuts	<u>S</u>
----	--	----------

Description of observation :

2	Cross Drainage Structure	<u>S</u>
a)	Condition of head walls in Hume pipe culverts	<u>S</u>
b)	Condition of Vent Clearance	<u>S</u>
c)	Condition of railings/Slab approach for Bridges	<u>NA</u>

Description of observation of CD works : R.C.C. Slab culvert not constructed due to both of at old damage HP culvert due to both sides of the road lodged flood water.

Remark if any:

Overall Rating:

Satisfactory (S) / Unsatisfactory (U)

Name of Officer: Bindu Rajak
 Designation: Executive Engineer
R.W.D.
Regional Lab. Darbhanga

12/07/21
A.E.

12/07/21
(Signature)