

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <i>Togaili - Teenmohani More</i>		
Hazards	Flood/Rain <i>Flood in 2020-21</i>	
Division: <i>Purnea</i>	District: <i>Purnea</i>	Actual Length (in km): <i>14.68</i>
Damage Length (in km): <i>Approx 0.050 in</i>	Damages Location/Chainage: <i>In Link Rd, 2.5 km ahead of the Road</i>	
Name of Scheme/Programme:		
Status of Project:	Under Agreement/Out of Agreement <i>Out of Agreement/Link Rd of Purnea</i>	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	—
Description of observation: <i>Surface work not done</i>		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation: <i>Base work and Sub base work not done</i>		
c)	Quality of Construction Material Used	—
Description of observation: <i>—</i>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation: <i>—</i>		
e)	Compaction of flanks/ slope & raincuts	U
Description of observation: <i>Temporary Restoration work had been found done at 2.5 km ahead of Togaili - Teenmohani more Rd (Link Rd - Purnea Rd) in flanks and below also damaged RCC culvert by Brick bats and Sandy Baffle and Soil etc with Bamboo etc.</i>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	<i>vent clear</i>
c)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works: <i>In Link Road, old RCC culvert is badly damaged almost flood.</i>		
Remark if any: <i>Temporary Restoration done only.</i>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory (U)

Name of Officer: *Rana Bansen Kumar Singh*
 Designation: *Executive Engineer.*
RWD, Regional Laboratory, Bikaner.

11/03/2021
 (Signature)