

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>Chellengipir to Kathkudga</u>		
Hazards	Flood/Rain <u>Flood in 2020-21</u>	
Division: <u>Purnea</u>	District: <u>Purnea</u>	Actual Length (in km): <u>4.2</u>
Damage Length (in km): <u>Approx. 0.020</u>	Damages Location/Channel: <u>3.4 km E/W 200m ahead in Link Road</u>	
Name of Scheme/Programme: <u>M/MHSY</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u> <u>Under Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	—
Description of observation: <u>Surface work not done</u>		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation: <u>Base work and subbase work not done.</u>		
c)	Quality of Construction Material Used	—
Description of observation: <u>—</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation: <u>—</u>		
Description of observation: <u>In approach of H.L Bridge in Link Road (ahead of 200m from main road) which was damaged due to flood by Brick Bats and sandy soil.</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	<u>clear</u>
c)	Condition of railings/Slab/approach for Bridges	<u>O.K</u>
Description of observation of CD works:		
Remark if any: <u>Restoration work done in flanks only.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory (U)

Name of Officer: Rana Badam Kumar Singh
 Designation: Executive Engineer
RWD, Regional Laboratory, Bhaupur.

03-03-2021
 (Signature)