

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme:	Rd 87 to Dalia ghut		
Hazards	Flood/Rain Flood in 2020-21		
Division:	District:	Actual Length (in km):	
Damage Length (in km):	Approx 80 m in R. Road	Approx 2.30 to 2.73	
Name of Scheme Programme:	MMBSY		
Status of Project:	Under Agreement/Out of Agreement Under Agreement		
Sl. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)	
1.	Pavement (BT/CC)		
a)	Condition of Surfacing	—	
Description of observation : Surface work not done.			
b)	Adequate Thickness of pavement layers constructed	—	
Description of observation : Base Work & Sub base work not done			
c)	Quality of Construction Material Used	—	
Description of observation : —			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—	
Description of observation : —			
e)	Compaction of flanks/slope & raincuts	U	
Description of observation : Restoration work had been found done in approx. 80 m (Right flank) only which was damaged due to Flood by Brick Bats and Sandy Soil.			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		
b)	Condition of Vent Clearance		
c)	Condition of railings/Slab/approach for Bridges		
Description of observation of CD works : —			
Remark if any: Restoration work done in flanks only. No need of Permanent Restoration on Surface work. (Surface not damaged due to flood.)			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory (U)

Name of Officer: Rana Ramesh Kumar Singh

Designation: Executive Engineer
RWD, Regional Laboratory, Bhagalpur.

10.04.2021
(Signature)