

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: RBO Road to Paduman chhapra			
Hazards		Flood/Rain	
Division: Chakia	District: Purvi Champaran	Actual Length (in km): 1.528 km	
Damage Length (in km): 0.298 km	Damages Location/Chainage:		
Name of Scheme/Programme:		FDR	
Status of Project:		Under Agreement/Out of Agreement Out of Agreement.	
Sr. No.		Parameters to be Checked in Restoration work	
1.		Pavement (BT/CC)	
a)		Condition of Surfacing	
Description of observation : CC pavement done in length 298 metre.			
b)		Adequate Thickness of pavement layers constructed	
Description of observation : 75mm WBM Gr III			
c)		Quality of Construction Material Used	
Description of observation : Good quality.			
d)		Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation :			
e)		Compaction of flanks/ slope & raincuts	
Description of observation :			
2		Cross Drainage Structure	
a)		Condition of head walls in Hume pipe culverts	
b)		Condition of Vent Clearance	
c)		Condition of railings/Slab/approach for Bridges	
Description of observation of CD works : No provision in the scheme.			
Remark if any: Restoration work completed.			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer:

Designation:

Ram Prabesh Saw.
TA, RWD
Work Circle Siwan.

(Signature)

13/7/21
AC