

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: LOBE - Futa Chalk to Rupa (along VR 61)

Hazards

Flood/Rain Flood in 2020-21

Division: Punjab

District: Punjab

Actual Length (in km): 3.428

Damage Length (in km): Approx 40m

Damages Location/Chainage: Approx 3.35 to 3.42

Name of Scheme/Programme:

PMBSY

Status of Project:

Under Agreement/Out of Agreement Under Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks: (S/U)

1.

Pavement (B/E/CC)

a)

Condition of Surfacing

Description of observation:

Surface work not done.

b)

Adequate Thickness of pavement layers constructed

Description of observation:

Base work and Subbase work not done.

c)

Quality of Construction Material Used

Description of observation:

d)

Whether free from any defects and Irregularity example: Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation:

e)

Compaction of flanks/ slope & raincuts

Description of observation:

Restoration work has been found done in approx 40m (Right Flank) length only by Brick Ball and Sandy Soil which was damaged by flood.

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

c)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works:

Remark if any: Restoration work done in flank only. No need of Permanent Restoration on surface work (Surface not damaged.)

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory (U)

Name of Officer: Rana Bawa Kumar Singh

Designation: Executive Engineer
RWD, Regional Laboratory, Bhopal.

(Signature)

10.13.2021