

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme:	Dabariya tola Bawali to Hamar tola		
Hazards	Flood/Rain Flood in 2020-21		
Division : Purnea	District: Purnea	Actual Length (in km): 1.17	
Damage Length (in km): Approx 0.100	Damages Location/Chainage: 0.150 to 0.200 & 200 to 200.320		
Name of Scheme/Programme:	MM658		
Status of Project:	Under Agreement/Out of Agreement Ongoing Scheme (not completed)		
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		
a)	Condition of Surfacing		—

Description of observation : Surface work not done.

b)	Adequate Thickness of pavement layers constructed	S
Description of observation : GSB gti work done in approximately, 100m length & 3.75m width having thickness 100 mm. This scheme is ongoing in which GSB work done only.		
c)	Quality of Construction Material Used	S
Description of observation : Quality of GSB material is satisfactory		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	—

Description of observation :

e)	Compaction of flanks/ slope & raincuts	S
Description of observation : No rain cuts in flank.		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
C)	Condition of railings/Slab/approach for Bridges	—

Description of observation of CD works :

Remark if any: Only GSB gti work done.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory (S)

Name of Officer: Rana Baran Kumar Singh

Designation: Executive Engineer

RWD, Regional Laboratory, Bhagalpur.

Date: 07.07.2021
(Signature)