

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Raghunathpur, Ward No. 06, Kamleshwar Yadav (Belahi Nayagarh) KE
 Hazards: Flood/Rain

Division: Madhepura

District: Madhepura

Actual Length (in km):

Damage Length (in km):

Damages Location/Chainage: 0.200 KM - (1 X 2.00 X 1.50) M
0.350 KM - (1 X 2.00 X 1.50) M
2 Nos - RCC culvert

Name of Scheme/Programme:

Status of Project:

Under Agreement/Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks: (S/U)

1.

Pavement (BT/CC)/RCC slab culvert

RCC slab culvert

a)

Condition of Surfacing

Description of observation:

Two nos of slab culvert work in progress.
(one number of slab culvert - Deck slab culvert)

b)

Adequate Thickness of pavement layers constructed

Description of observation:

c)

Quality of Construction Material Used

Description of observation:

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation:

e)

Compaction of flanks/ slope & raincuts

Description of observation:

2

Cross Drainage Structure

In progress

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

c)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works:

Remark if any:

Two nos. of slab culvert work in progress.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, R. Lab Gultzarbag, Patna

12/07/2021

(Signature)