

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: <u>Tikuliya Hat to Laxmipur Bhagwati word Bank Road</u>		Hazard: <u>Flood/Rain</u>	
Division: <u>Madhepura</u>		District: <u>Madhepura</u>	
Damage Length (in km): <u>0.487</u>		Actual Length (in km): <u>10.000</u>	
Name of Scheme/Programme:		Damages Location/Chainage: <u>0.000KM - 0.010KM, 1.800KM - 1.354KM, 2.100KM - 2.170KM, 2.300KM - 2.395KM, 2.625KM - 2.661KM, 3.600KM - 3.672KM, 4.400KM - 4.449KM, 5.100KM - 5.132KM, 5.600KM - 5.628KM, 6.200KM - 6.261KM, 6.600KM - 6.636KM & 7.150KM - 7.174KM</u>	
Status of Project:		Under Agreement/Out of Agreement ☒	
Sr. No.		Parameters to be Checked in Restoration work	
1.		Pavement (BT/CC)	
a)		Condition of Surfacing	
Description of observation :		Remarks : (S/U)	
b)		Adequate Thickness of pavement layers constructed	
Description of observation :		S	
c)		Quality of Construction Material Used	
Description of observation :		S	
d)		Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship. etc.	
Description of observation :		—	
e)		Compaction of flanks/ slope & raincuts	
Description of observation :		—	
2		Cross Drainage Structure	
a)		Condition of head walls in Hume pipe culverts	
b)		Condition of Vent Clearance	
c)		Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		NA	
Remark if any:			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>Satisfactory</u>
---------------------------------------	---------------------

Name of Officer: Ram Kumar Mishra

Designation: EE, R. lab, Gulzashag Satna

11/07/2021 (Signature) 11/07/2021