

# INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme: Shaukarpur To Bathani Pass

Hazards: Flood/Rain

Division: Madhepura

District: Madhepura

Actual Length (in km): 5.100

Damage Length (in km): 0.128

Damages Location/Chainage: 0.700KM - 0.708KM & 4.910KM - 5.020KM

Name of Scheme/Programme:

Status of Project: Under Agreement/Out of Agreement

| Sr. No. | Parameters to be Checked in Restoration work | Remarks : (S/U) |
|---------|----------------------------------------------|-----------------|
| 1.      | Pavement (BT/CC)                             | BT              |
| a)      | Condition of Surfacing                       | S               |

Description of observation :

|    |                                                   |   |
|----|---------------------------------------------------|---|
| b) | Adequate Thickness of pavement layers constructed | S |
|----|---------------------------------------------------|---|

Description of observation :

|    |                                       |   |
|----|---------------------------------------|---|
| c) | Quality of Construction Material Used | S |
|----|---------------------------------------|---|

Description of observation :

|    |                                                                                                                                                       |   |
|----|-------------------------------------------------------------------------------------------------------------------------------------------------------|---|
| d) | Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. | - |
|----|-------------------------------------------------------------------------------------------------------------------------------------------------------|---|

Description of observation :

|    |                                        |   |
|----|----------------------------------------|---|
| e) | Compaction of flanks/ slope & raincuts | - |
|----|----------------------------------------|---|

Description of observation :

|   |                          |     |
|---|--------------------------|-----|
| 2 | Cross Drainage Structure | N/A |
|---|--------------------------|-----|

|    |                                               |
|----|-----------------------------------------------|
| a) | Condition of head walls in Hume pipe culverts |
|----|-----------------------------------------------|

|    |                             |
|----|-----------------------------|
| b) | Condition of Vent Clearance |
|----|-----------------------------|

|    |                                                 |
|----|-------------------------------------------------|
| c) | Condition of railings/Slab/approach for Bridges |
|----|-------------------------------------------------|

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Designation:

Ram Kumar Mishra

EE, R. Lab, Gulzarbag Salim

11/07/2021

11/07/2021