

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme:	Dinapatti Nadi Murho Madhuban Road		
Hazards	Flood/Rain		
Division :	Madhepura	District:	Madhepura
Damage Length (in km):	1.053	Actual Length (in km):	11.465 km
Name of Scheme/Programme:			
Status of Project:	Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		BT
a)	Condition of Surfacing		S

Description of observation :

b)	Adequate Thickness of pavement layers constructed	S
----	---	---

Description of observation :

c)	Quality of Construction Material Used	S
----	---------------------------------------	---

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
----	---	---

Description of observation :

e)	Compaction of flanks/ slope & raincuts	—
----	--	---

Description of observation :

2	Cross Drainage Structure	N.A.
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, R. Lab Gulerbag, Patna

12/07/2021

(Signature) 12/07/2021