

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Sambarsa to Shankarpur

Hazards: Flood/Rain

Division: Madhepura

District: Madhepura

Actual Length (in km): 6.370

Damage Length (in km): 0.766

Damages Location/Chainage: 2.250-2.383, 2.500-2.579, 2.580-2.609, 2.830-2.917, 3.500-3.680, 3.800-3.862, 4.360-4.403, 4.630-4.766, 4.800-4.860, 5.700-5.750.

Name of Scheme/Programme:

Status of Project: Under Agreement/Out of Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks: (S/U)

1. Pavement (BT/CC) BP

a) Condition of Surfacing S

Description of observation :

b) Adequate Thickness of pavement layers constructed S

Description of observation :

c) Quality of Construction Material Used S

Description of observation :

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. -

Description of observation :

e) Compaction of flanks/ slope & raincuts -

Description of observation :

2 Cross Drainage Structure N/A

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, R. Lab Gubarkhag, Patna

11/07/2021 (Signature) 11/07/2021