

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: ROSHNAMA TOLA MALBIGHA (POTHIYA) TO HALBAILA

Hazards: Flood/Rain

Division: District: Actual Length (in km): 2.10 KM

Damage Length (in km): 1.10 KM Damages Location/Chainage:

Name of Scheme/Programme: MMGSY

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks
1.	Pavement (BT/CC)	<u>U</u>
a)	Condition of Surfacing	<u>U</u>

Description of observation: Laying and rolling temperature was not maintained. Disintegrations found.

b) Adequate Thickness of pavement layers constructed S

Description of observation:

c) Quality of Construction Material Used S

Description of observation:

d) Whether free from any defects and irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. N/A

Description of observation:

e) Compaction of flanks/slope & raincuts ✓

Description of observation:

2 Cross Drainage Structure

a) Condition of head walls in Flume pipe culverts N/A

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works:

Remark if any: MSS surface found disintegrated. Laying and rolling temp. was not maintained.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Name of Officer: KUMAR RAKESH

Designation:

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature)

12.07.21