

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Mangalgash to Dudhpura
 Hazards: Flood/Rain
 Division: Rosera District: Samastipur Actual Length (in km): 1.250
 Damage Length (in km): 0.660 Damages Location/Chainage:
 Name of Scheme/Programme: FDR
 Status of Project: Under Agreement/Out of Agreement

Sr. No. 1. Parameters to be Checked in Restoration work
 a) Pavement (BT/CC) BT Remarks: (S/U)
 Condition of Surfacing S

Description of observation : Good

b) Adequate Thickness of pavement layers constructed S

Description of observation : M.S.S thickness - 20 mm.

c) Quality of Construction Material Used S

Description of observation : Satisfactory.

d) Whether free from any defects and irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. S

Description of observation : No defect

e) Compaction of flanks/slope & raincuts S

Description of observation :

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works : No provision in this estimate

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer: Mahesh Pd Gupta

Designation: EE, RWD, Regional Lab
Patna

18/7/2021
 (Signature)