

(1)

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: Jhagtharpur Madhepur Mukhya Path to Kalithainiya Dargah		
Hazards		Flood/Rain Flood
Division: Jhagtharpur	District: Madhubani	Actual Length (in km): 1.00 km.
Damage Length (in km): 0.350 km	Damages Location/Chainage:	
Name of Scheme/Programme:		F.D.R
Status of Project:		Under Agreement/Out of Agreement
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	CC
a)	Condition of Surfacing	S
Description of observation : CC Surface found in good condition.		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation : Adequate thickness found		
c)	Quality of Construction Material Used	S
Description of observation : Good quality of Material used		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	S
Description of observation : Found in good condition.		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : Flank work in progress.		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	NA
b)	Condition of Vent Clearance	S
c)	Condition of railings/Slab/approach for Bridges	NA
Description of observation of CD works : NA		
Remark if any:		
Overall Rating		

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

19/7/21
A.E.

19/7/21
(Signature)