

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme: Penihara MMWSY Road to Bugjog Tola

Hazards: Flood/Rain Division: Darbhanga-2 District: Darbhanga Actual Length (in km): 0.990

Damage Length (in km): 0.020 Damages Location/Chainage:

Name of Scheme/Programme: FDR, Permanent Restoration work

Status of Project: Under Agreement/Out of Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks: (S/U)

1. Pavement (BT/CC)

a) Condition of Surfacing

Description of observation :

b) Adequate Thickness of pavement layers constructed

Description of observation :

c) Quality of Construction Material Used

Description of observation :

d) Whether free from any defects and irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation :

e) Compaction of flanks/ slope & raincuts

Description of observation :

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any: Permanent Restoration work not done. Request for cancellation of AA vide letter No. 674 (M3) 2/6/2021 E.E R.W.D. Darbhanga to S.E. R.W.D. Darbhanga Circle, Road is under 5 yrs. maintenance period.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Sri Kant Prasad

Name of Officer:

E.E

S.A.
20/7/2021
A.E.

1373
20/7/2021