

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: BIRPUR TO RAMBAGH
 Hazards: Flood/Rain FLOOD
 Division: JHANSARPUR District: MADHUBANI Actual Length (in km): 3.400KM
 Damage Length (in km): 0.383KM Damages Location/Chainage:

Name of Scheme/Programme: F.A.R.
 Status of Project: Under Agreement/Out of Agreement

| Sr. No. | Parameters to be Checked in Restoration work | Remarks : (S/U) |
|---------|----------------------------------------------|-----------------|
| 1. | Pavement (BT/CC) <u>BT</u> | |
| a) | Condition of Surfacing | <u>S</u> |

Description of observation : BT Surface found in good condition

| | | |
|----|---------------------------------------------------|----------|
| b) | Adequate Thickness of pavement layers constructed | <u>S</u> |
|----|---------------------------------------------------|----------|

Description of observation : Adequate Thickness found

| | | |
|----|---------------------------------------|----------|
| c) | Quality of Construction Material Used | <u>S</u> |
|----|---------------------------------------|----------|

Description of observation : Good Quality of Material used

| | | |
|----|-------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| d) | Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. | |
|----|-------------------------------------------------------------------------------------------------------------------------------------------------------|--|

Description of observation : NA

| | | |
|----|----------------------------------------|--|
| e) | Compaction of flanks/ slope & raincuts | |
|----|----------------------------------------|--|

Description of observation : Flank work in Progress

| | | |
|---|--------------------------|--|
| 2 | Cross Drainage Structure | |
|---|--------------------------|--|

| | | |
|----|-----------------------------------------------|-----------|
| a) | Condition of head walls in Hume pipe culverts | <u>NA</u> |
|----|-----------------------------------------------|-----------|

| | | |
|----|-----------------------------|----------|
| b) | Condition of Vent Clearance | <u>S</u> |
|----|-----------------------------|----------|

| | | |
|----|-------------------------------------------------|-----------|
| c) | Condition of railings/Slab/approach for Bridges | <u>NA</u> |
|----|-------------------------------------------------|-----------|

Description of observation of CD works : NA

Remark if any:

Overall Rating

| | |
|---------------------------------------|----------|
| Satisfactory (S) / Unsatisfactory (U) | <u>S</u> |
|---------------------------------------|----------|

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

20/7/24
(Signature)