

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme:	RED Road To fulwareya	Hazards	Flood/Rain
Division:	Darbhanga-1	District:	Darbhanga
Damage Length (in km):	1.300	Actual Length (in km):	1.595
Name of Scheme/Programme:		Damages Location/Chainage: 0.295 KM — 1.595 KM	
Status of Project:		Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		B/T
a)	Condition of Surfacing		S

Description of observation :

b)	Adequate Thickness of pavement layers constructed	S
----	---	---

Description of observation :

c)	Quality of Construction Material Used	S
----	---------------------------------------	---

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	—
----	--	---

Description of observation :

e)	Compaction of flanks/ slope & raincuts	—
----	--	---

Description of observation :

2	Cross Drainage Structure	N/A.
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)


Satisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, R-Lab Gularbagh, Patna

Q 
20/07/2021 (Signature)