

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme: MALIBADI TO CHANDPUR ROAD		
Hazards	Flood/Rain	
Division: SITAMARHI	District: SITAMARHI	Actual Length (in km): 1.690 KM
Damage Length (in km): 0.150 KM	Damages Location/Chainage:	
Name of Scheme/Programme:	PMGSY (OLD)	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (%)
1.	Pavement (BT/CC)	S
a)	Condition of Surfacing	S
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N/A
Description of observation :		
e)	Compaction of flanks/slope & raincuts	-
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts.	N/A
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: Work done found satisfactory.		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: **KUMAR RAKESH**

Designation:

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature)

19.07.2021