

# INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme:	REO Road to Nautoliya		
Hazards	Flood/Rain		
Division:	Darbhanga-1	District: Darbhanga	Actual Length (in km): 0.385
Damage Length (in km):	0.275	Damages Location/Chainage (in Km): 0.000 — 0.105, 0.145 — 0.190 0.250 — 0.375	
Name of Scheme/Programme:			
Status of Project:	Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		CC
a)	Condition of Surfacing		U

Description of observation : work has not been started.

b)	Adequate Thickness of pavement layers constructed	—
----	---	---

Description of observation :

c)	Quality of Construction Material Used	—
----	---------------------------------------	---

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
----	---	---

Description of observation :

e)	Compaction of flanks/ slope & raincuts	—
----	--	---

Description of observation :

2	Cross Drainage Structure	N.A
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	

Description of observation of CD works :

Remark if any: work has not been started.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	Unsatisfactory
---------------------------------------	----------------

Name of Officer: Ram Kumar Mishra

Designation: EE, R. Lab. Gulzarbagh, Patna

(S)  
20/07/2021

Unsatisfactory

(Signature)

20/07/2021