

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme:		Ata Pur to Kundah	
Hazards		Flood/Rain	
Division :	Resera	District:	Semoshpur
Damage Length (in km):	0.970	Actual Length (in km):	1.80
Name of Scheme/Programme:		Damages Location/Chainage:	
Status of Project:		Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		BT
a).	Condition of Surfacing		S
Description of observation :			
Good.			
b)	Adequate Thickness of pavement layers constructed		S
Description of observation :			
20 mm BT thickness.			
c)	Quality of Construction Material Used		S
Description of observation :			
Satisfactory			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.		S
Description of observation :			
No defect			
e)	Compaction of flanks/ slope & raincuts		
Description of observation :			
No Provision			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		
b)	Condition of Vent Clearance		
c)	Condition of railings/Slab/approach for Bridges		
Description of observation of CD works :			
No Provision			
Remark if any:			
Work done is in good position.			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Mohesh Pd. Gupta

Designation:

EE, RWD, Regional. Lab
Purnea

(Signature)

23/2/2017