

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: <u>Rosera - Shiva Tinagar to Jatcha</u>		Flood/Rain	
Hazards		District: <u>Samastipur</u>	
Division: <u>Rosera</u>	Damage Length (in km): <u>9.40 km</u>	Actual Length (in km): <u>9.40 km</u>	
Name of Scheme/Programme: <u>FDR</u>		Damages Location/Chainage:	
Status of Project:		Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work		Remarks: (S/U)
1.	Pavement (BT/CC)		
a)	Condition of Surfacing		
Description of observation:			<u>S</u>
<u>Good.</u>			
b)	Adequate Thickness of pavement layers constructed		
Description of observation:			<u>S</u>
<u>M. ss - 20 mm thickness</u>			
c)	Quality of Construction Material Used		
Description of observation:			<u>S</u>
<u>Satisfactory</u>			
d)	Whether free from any defects and irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.		
Description of observation:			<u>S</u>
<u>No defect</u>			
e)	Compaction of flanks/ slope & raincuts		
Description of observation:			
<u>No provision</u>			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		
b)	Condition of Vent Clearance		
c)	Condition of railings/Slab/approach for Bridges		
Description of observation of CD works:			
<u>No provision</u>			
Remark if any: <u>work done is in good condition.</u>			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Mahesh Pd Gupta.

Designation:

EE, RWD, Regional Lab.
Purnea

[Signature]
(Signature) 19/07/2024