

# INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Nandan Nagar Sahni House To Ganga Suroch Singh House

Hazards: Flood/Rain

Division: Muz. East-2

District: Muzaffarpur

Actual Length (in km): 1.375

Damage Length (in km): 0.360 km

Damages Location/Chainage: 390, 1240, 1365

Name of Scheme/Programme: F.D.R (3054)

Status of Project: Under Agreement/Out of Agreement

| Sr. No. | Parameters to be Checked in Restoration work | Remarks : (S/U) |
|---------|----------------------------------------------|-----------------|
| 1.      | Pavement (BT/CC)                             | <u>B.T.</u>     |
| a)      | Condition of Surfacing                       | <u>S</u>        |

Description of observation : M.S.S. Surfacing is in good condition

b) Adequate Thickness of pavement layers constructed

S

Description of observation :  
G.S.B - 175 mm  
W.B.M II - 75 mm  
M.S.S. - 20 mm

c) Quality of Construction Material Used

S

Description of observation : Good quality material used

d) Whether free from any defects and Irregularity example-  
 Surface Cracks, Undulation, exposed aggregates in case of  
 CC Pavement, Poor workmanship, etc.

N.A

Description of observation : N.A.

e) Compaction of flanks/slope & raincuts

S

Description of observation : Flank work is in good condition

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance

S

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works :  
R.C.C culvert is in good condition

Remark if any: B.T. work done in 0.360 km

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer:

AKH/  
21/07/2021  
AB

21/07/21  
21-7-21  
E-E