

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme:	T03 To Bakhai Tale		
Hazards	Flood/Rain	Actual Length (in km):	0.610
Division:	Darbhangha-1	District:	Darbhangha
Damage Length (in km):	0.250	Damages Location/Chainage:	0.400 - 0.650, 0.120 - 0.220, 0.240 - 0.440
Name of Scheme/Programme:			
Status of Project:	Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work		Remarks (S/U)
1.	Pavement (BT/CC)		CC
a)	Condition of Surfacing		
Description of observation : The work site is not approachable			
b)	Adequate Thickness of pavement layers constructed		
Description of observation :			
c)	Quality of Construction Material Used		
Description of observation :			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.		
Description of observation :			
e)	Compaction of flanks/ slope & raincuts		
Description of observation :			
2	Cross Drainage Structure		N.A.
a)	Condition of head walls in Hume pipe culverts		
b)	Condition of Vent Clearance		
c)	Condition of railings/Slab/approach for Bridges		
Description of observation of CD works :			
Remark if any: The work site is not approachable.			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, R. Lab. Gulsarbag, Satna

Signature
19/07/2024