

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Bodhnagar To Godaipatti

Hazards Flood/Rain

Division: Darbhanga-1

District: Darbhanga

Actual Length (in km): 4.017

Damage Length (in km): 1.000

Damages Location/Chainage: 0.150 — 0.250, 0.350 — 0.750, 1.200 — 1.450, 1.800 — 2.050 (2.0 KM)

Name of Scheme/Programme:

Status of Project:

Under Agreement/Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks: (S/U)

1.

Pavement (BT/CC)

BT

a)

Condition of Surfacing

S

Description of observation:

Only 0.100 KM work has been done out of 1.000 KM damaged length

b)

Adequate Thickness of pavement layers constructed

S

Description of observation:

c)

Quality of Construction Material Used

S

Description of observation:

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

—

Description of observation:

e)

Compaction of flanks/ slope & raincuts

—

Description of observation:

2

Cross Drainage Structure

NA.

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

C)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works:

Remark if any:

Only 0.100 KM work has been done out of 1.000 KM — damaged length

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, Lab and Survey, Patna

(R)

10/7/21