

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Harichanda To Kale Ambedkar Nagar
 Hazards: Flood/Rain
 Division: Darbhanga-1 District: Darbhanga Actual Length (in km): 5.140
 Damage Length (in km): 1.600 Damages Location/Chainage: 0.200 — 1.800
 Name of Scheme/Programme: (in km)
 Status of Project: Under Agreement/Out of Agreement
 Sr. No. Parameters to be Checked in Restoration work Remarks: (S/U)
 1. Pavement (BT/CC) BT
 a) Condition of Surfacing —

Description of observation :

b) Adequate Thickness of pavement layers constructed —

Description of observation :

c) Quality of Construction Material Used —

Description of observation :

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. —

Description of observation :

e) Compaction of flanks/ slope & raincuts —

Description of observation :

2 Cross Drainage Structure N.A.
 a) Condition of head walls in Hume pipe culverts
 b) Condition of Vent Clearance
 c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any: The work site was not approachable due to flood water

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Unsatisfactory

Name of Officer: Ram Kumar Mishra

Designation: EE, R. Lab. Gulzarbag, Patna

19/07/2021 (Signature) 19/07/2021