

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: Buj stand to pyrab mahadalit Tola, Sak to 9 Tak		
Hazards	Flood/Rain	
Division : Trivenigari	District: Supaul	Actual Length (in km): 2.300
Damage Length (in km): 0.020	Damages Location/Chainage: —	
Name of Scheme/Programme:		
Status of Project:	Under Agreement/Out of Agreement <u>out of agreement</u>	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	—
a)	Condition of Surfacing	
Description of observation : —		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation : —		
c)	Quality of Construction Material Used	—
Description of observation : —		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation : —		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation : —		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	S
b)	Condition of Vent Clearance	S
c)	Condition of railings/Slab/approach for Bridges	U
Description of observation of CD works : In the DPR 2 nos Hume pipe culvert (Two row 1000 dia) with approach road in 20m is to be constructed. one no HP culvert constructed.		
Remark if any: In one no HP culvert, painting of parapet and construction of approach road is not complete. In one HP culvert construction not started.		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	U
---------------------------------------	---

Name of Officer: Ramprabesh Saw
 Designation: J. N. R. W. D E Work
 Circle Siwan

[Signature]
 22/7/2024
 A.E- (Signature) 22.7.21