

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: Khara Brahmanola Gramin Bank Chouk to Mangla Hathi Raghunath		
Hazards	Flood/Rain	
Division: Uda Kishungari	District: Madhepura	Actual Length (in km): 2.355
Damage Length (in km): 1.8	Damages Location/Chainage:	
Name of Scheme/Programme:	FDR	
Status of Project:	Under Agreement/Out of Agreement out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S
Description of observation: 20 mm mix Seal surface done in about 1.8 km length		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation: 20 mm mix Seal Surface.		
c)	Quality of Construction Material Used	S
Description of observation: 20 mm mix Seal Surface good quality.		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	U
Description of observation: At end point and at approach of culverts two places, undulation are existing		
e)	Compaction of flanks/ slope & raincuts	
Description of observation: There is provision of E/W in both flanks in 1.8 km length. But earth work is not completed.		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	-
b)	Condition of Vent Clearance	-
c)	Condition of railings/Slab/approach for Bridges	-
Description of observation of CD works: No provision of CD works		
Remark if any: E/W in flank is not completed. In the estimate Logo Board is sanctioned, But not found at site.		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	U
---------------------------------------	---

Name of Officer: Ram Prakesh Sah
 Designation: T.N. R. W. D WORK
 Guler Siwan.

24.7.21
 AE.

24.7.21
 (Signature)