

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme: LD 73 - Siwan Pathi To Lantun (VR-68)

Hazards: Flood/Rain

Division: Muz East-2 District: Muzaffarpur Actual Length (in km): 16.612 km

Damage Length (in km): 1.183 km Damages Location/Chainage: 80.1 km

Name of Scheme/Programme: FDR (3054)

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) <u>B.T.</u>	
a)	Condition of Surfacing	<u>U</u>

Description of observation : M.SS Surfacing is done in 1.183 km but disintegrated in 12m length at curve

b) Adequate Thickness of pavement layers constructed S

Description of observation : G.S.B - 15 - 175 mm
W.B.M Gr II - 75 mm
M.SS - 20 mm

c) Quality of Construction Material Used S

Description of observation : Good Quality material used

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. N.A.

Description of observation : N.A.

e) Compaction of flanks/ slope & raincuts S

Description of observation : Flank is in good condition

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts N.A.

b) Condition of Vent Clearance N.A.

c) Condition of railings/Slab/approach for Bridges N.A.

Description of observation of CD works : N.A.

Remark if any: M.SS. Surfacing disintegrated in 12m length at corner

Overall Rating

Satisfactory (S) / Unsatisfactory (U) U

Name of Officer:

Designation:

AKB
21/07/2021
AE

21-7-21
(Signature)
E.E