Inspection Report for Flood Damage Work

			100		
1	r	١.	. 1	-	
9		J c	11	C	

2. Name of Block/Road - mina burs/ phashipatty pwo se saharz burs reathe fall

A. Fer Road

: 0.030 km, 0.200 km 1. Damage Location/Chainage

: 0.047 Km 2. Damage Length

3. Nature of Damage

4. Details of Restoration Works

Brick buts Material being used in Restoration works:

Equipments/Tools being used in Restoration works: Tracetob ii.

Procedure taken up in Restoration works: iii.

Restored Length : 0.047/em iv.

B. For Bridge

1. Damage Location/Chainage

2. Damage Length

3. Nature of Damage

4. Details of Restoration Works

Material being used in Restoration works:

Equipments/Tools being used in Restoration works:

Procedure taken up in Restoration works:

iv. Restored Length

Signature of JE/AE/EE

(Name of Inspector) कार्यपोलक अधियंता प्रामीण कार्य विभाग कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1

	R.W.D.(W) Sub Division,Minapu NAME OF WORK : Dhahipatty PWD s	e sahazpi	ur kotile tak	Rate per	Amount
		Unit	Qty.	Unit	
SI.No.	Description of Work Supplying ,laying & spreading of Brick bats at work at site including all cost of Tax and	M ³	2034.90	2033.34	4137644
2	Royalties etc. Providing and Laying Reinforced Cement Concrete Pipe NP3 1000 mm dia as per desing	RM	5.00	3594.14 nd Total Rs.	17971 4155615

say 41.56 lath

JE(RWD) Muz. East-2

ASIZVIUM AE(RWD) Muz. East-2 EE(RWD) Muzl East-2

Technically sametion for RS 41.56 lakh
(Rupees forty one latch fifty sox thousand only)

अधीषाण अभियंता ग्रामीण कार्य विभाग कार्य अंवल, मुजप्फरपुर