Inspection Report for Flood Damage Work

Date: 1 Name of PIUs:- Gyan vibhatour 2 Name of Block/Road:- Aurai | Amnour Hathauna road to Thiktahi (A) For Road:

- 1. Damage Location/Chainage :- many places
 2. Damage Length :- 0.44263 km
- 3. Nature of Damage :-4. Details of Restoration Works :-
- (i) Material being used in Restoration works: Brick bats
- (ii) Equipment's/Tools being used in Restoration works:- Tractor.
- (iii) Procedure taken up in Restoration works:
- (iv) Restored Length :- 0.44263 Km

(B) For Bridge:

- 1. Damage Location/Chainage :-
- 2. Damage Length :
- 3. Nature of Damage :
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

Signature
(Name of Inspection)
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल,मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

Amnaur Hathauna Road to Jhiktahi

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

1.967 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0,000
2	Jhama metal	6.519
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	0.180
	GRAND SUB TOTAL	6.699
TOTAL C	OST OF PROJECT IN LACS =	6.699

514

RWD

Technically approved for RS 6.699 lac (Rupees six lac sixty nine thousand nine hundred only)

अधीक्षण अभियंता
ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरपुर