

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar
2 Name of Block/Road :- 100ft / under Tehwara Panchayat Vinod Makto Houde to
Budhkar Sinar

(A) For Road:

1. Damage Location/Chainage :- 1.010 km
2. Damage Length :- 0.052 km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick ball
 - (ii) Equipment's/Tools being used in Restoration works:- Trencher
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.052 km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

Signature

(Name of Inspection)

EE

RWD muzaffarpur Galt-1

GENERAL ABSTRACT

Name of Road Under Tehwara Panchayat Vinod Mahto House to Budhkara Siman

District Muzaffarpur

Block Katra

Division Muzaffarpur East-2

Length of Road (in Km) 1.091 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Jhama metal	29.198
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	0.809
	GRAND SUB TOTAL	30.006
TOTAL COST OF PROJECT IN LACS =		30.006

say 30.00 lac

[Signature]
11/1/21

JE
RWD

[Signature]
11.11.2021

AE
RWD

[Signature]
11/1/21
EE
RWD

*Technically approved for Rs 30.00 lac
(Rupees Thirty lac only)*

[Signature]
13.1.21
SE

RWD work circle
muzaffarpur